




$$\begin{aligned} \text{PC} \quad & 800 - (270 + 60 + 40) = 430 & \text{Diff } C\_H &= 10 \\ \text{PH} \quad & 800 - (270 + 60 + 50) = 420 \end{aligned}$$

$$\begin{aligned} \text{PD} \quad & 800 - (270 + 60 + 40 + 40) = 390 & \text{Diff } D\_I &= 20 \\ \text{PI} \quad & 800 - (270 + 60 + 50 + 50) = 370 \end{aligned}$$

$$\begin{aligned} \text{PE} \quad & 800 - (270 + 60 + 40 + 40 + 30) = 360 & \text{Diff } E\_J &= 30 \\ \text{PJ} \quad & 800 - (270 + 60 + 50 + 50 + 40) = 330 \end{aligned}$$

$$\begin{aligned} \text{PF} \quad & 800 - (270 + 60 + 40 + 40 + 30 + 40) = 320 & \text{Diff } E\_J &= 30 \\ \text{PK} \quad & 800 - (270 + 60 + 50 + 50 + 40 + 40) = 290 \end{aligned}$$

$$\text{PG} \quad 800 - (270 + 60 + 40 + 40 + 30 + 40 + 40) = 280$$

$$\text{PL} \quad 800 - (270 + 60 + 50 + 50 + 40 + 40 + 50) = 240 \quad \text{Diff } E\_J = 40$$